

From: [Walzer, Thomas](#)
To: [Moore, Gary](#)
Cc: c.shappee@westonsolutions.com; [Latham, Benjamin](#)
Subject: Leaking or potential Overtops
Date: Wednesday, August 06, 2014 7:06:00 AM
Attachments: [removed.txt](#)

Based on locations in May 24, 2014 diagram.

1. Pool by Box 406 (on map maybe 403) Plastic stretched by what appears to be rain water. Plastic ripping.
2. Cluster of 4 drums north of Box 406 (on map maybe 403) and RO No ID - two are full on the lid rusted through the other appears to be leaking from seal.
3. Salvage drum No lid full, Liquid clear but there is a submerged drum of unknown contents in the drum.
4. Plastic on big tank is back pulling in.



Thomas Walzer

Principal Project Scientist

Weston Solutions, Inc.

an employee-owned company

5599 San Felipe, Suite 700

Houston, Texas 77056

(713) 985.6741 Direct

(713) 705.1467 Cell

(713) 985.6703 Fax

t.a.walzer@westonsolutions.com

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.

***** ATTACHMENT REMOVED

This message contained an attachment which the administrator has caused to be removed.

***** ATTACHMENT REMOVED

Attachment name: [image001.jpg]
Attachment type: [image/jpeg]